

To: Garmin Aviation Dealers  
From: Matthew Harrah, Director, Avionics Product Support  
Date: July 21, 2010

## **Discontinued Repair on GNS 430 28V, GNS 530 28V, and GTX 320 German**

Effective September 30, 2010, the GNS 430 28V, GNS 530 28V, and the GTX 320 German will no longer be repaired due to parts availability issues.

### **Affected Part Numbers**

011-00280-00 GNS 430 28V (010-00139-00/01)  
011-00550-00 GNS 530 28V (010-00182-00/01)  
011-00259-15 GTX 320 German (010-00135-15)

The GNS 430 and the GNS 530 will still be applicable for WAAS upgrade, provided no additional repairs are required for non-WAAS parts that are no longer available. Standard WAAS upgrade prices apply.

## **Discontinued Service Parts on GNS 430 28V, GNS 530 28V, and GTX 320 German**

Effective September 30, 2010, Service Parts for the GNS 430 28V, GNS 530 28V, and the GTX 320 German will no longer be available.