

GARMIN® G1000 SPARES



| Model: | Part Number: | Exchange Price: | Outright Price: |
|-----------|--------------|-----------------|-----------------|
| GDC-74B | 011-01110-01 | \$1550 | \$3950 |
| GDU-1040A | 011-00916-10 | \$2400 | \$6250 |
| GDU-1042 | 011-01080-00 | \$2550 | \$5250 |
| GDU-1043 | 011-01079-00 | \$2400 | \$6250 |
| GDU-1044B | 011-01274-10 | \$1950 | \$7750 |
| GDU-1050 | 011-03470-00 | \$2950 | \$6500 |
| GEA-71 | 011-00831-00 | \$950 | \$1995 |
| GIA-63W | 011-01105-00 | \$2250 | \$8450 |
| GTX-33 | 011-00779-10 | N/A | \$1050 |
| GTX-33ES | 011-00779-30 | \$1350 | \$2100 |
| GMA-36 | 011-01793-00 | \$1450 | \$5220 |
| GRS-77 | 011-00868-10 | \$1450 | \$2750 |

- ➔ G1000 Component Spares
- ➔ Garmin Certified 8130
- ➔ SV Condition with 6 Month Warranty