

Honeywell

hereby appoints

Southeast Aerospace, Inc.

Melbourne, FL

as an

Authorized Avionics Dealer

which meets the standards required to perform the following Service Categories:

- | | | | |
|-----|--|-----|--|
| 01 | SC NAV/COMM/ADF/ILS/Audio/MKR Beacon | 10 | Radar Altimeter (KRA 405/B) Bench Repair |
| 01B | SC GPS Long Range NAV Bench Repair | 10C | AA300, AM250 System Install/Troubleshoot to LRU |
| 01C | SC GPS Long Range NAV System Install/Troubleshoot | 15 | TCAS I System Troubleshoot to LRU |
| 02 | SC Transponder/DME/RNAV Bench Repair | 15A | Mark V GPWS System Troubleshoot to LRU |
| 02A | KT70/71 Mode S Transponder Bench Repair | 15B | Mark VI, Mark VIII, Mark XXII EGPWS System Troubleshoot to LRU |
| 03 | Primus II Radios System Install/Troubleshoot to LRU | 15C | Mark VII GPWS System Troubleshoot to LRU |
| 03A | GC NAV/COMM/ADF/ILS/Audio/MKR Beacon Bench Repair | 15D | TCAS II System Troubleshoot to LRU, ACAS |
| 03C | GC High Frequency Bench Repair | 15E | Data Recorders-SSFDR and SSCVR System Install/Troubleshoot to LRU |
| 04 | GC Transponder/DME/RNAV Bench Repair | 17 | Airsat 1 Satcom System Installation & System Troubleshoot |
| 05A | KAP/KFC 200 FCS, KCS 55A Compass System Bench Repair | 17B | SCS-1000 System Install/Troubleshoot to LRU |
| 07 | Gyros, HSI/OBS Electro-mechanicals Bench Repair | 20D | GNS-XLS NAV Systems Install/Troubleshoot, AFIS |
| 07A | OBS Electro-mechanicals Bench Repair | 20F | FMS-2000 Flight Man. Sys, HT9000/9100-Sys Install/Troubleshoot LRU |
| 07B | Certification of Remote Air Data Systems Bench Repair | 50 | Single Engine and Light Twin NAV/COMM/Pulse |
| 08 | Safety Prods GA/EGPWS Displays Sys Repair Install/Troubleshoot LRU | 51 | Heavy Twin and Turbine NAV/COMM/Pulse |
| 08A | Integrated Hazard Avoidance System Repair | 52 | Single Engine and Light Twin Safety Products |
| 09 | P440/660/880/700/701, LSZ 860, MFRD, Data Nav Sys Install/Troubleshoot LRU | 53 | Heavy Twin and Turbine Safety Products |
| 09A | RDS Series Weather Radar Bench Repair | 54 | Single Light Twin Autopilots |
| 09C | RDR 2000/2100 Weather Radar Bench Repair | 55 | Heavy Twin Turbines Autopilots |