

## Southeast Aerospace

FAA/EASA APPROVED REPAIR STATION # S66R266N 1399 General Aviation Drive Melbourne Intl. Airport Melbourne, FL 32935 USA Tel 321-255-9877 Fax 321-255-9608 Email sales@seaerospace.com www.seaerospace.com





**BEFORE** 

**AFTER** 

## **Robinson R-22 Installation**

July 2006

Southeast Aerospace recently completed a unique modification project on the Robinson R22 helicopter.

This VFR trainer helicopter was equipped with the new Sandel SN3500 Electronic HSI. The helicopter will be used for IFR training operations. Interfaced to the SN3500 included a newly installed Bendix/King KG-102A dir. gyro and KMT-112 flux valve along with the existing Garmin GNS-430 GPS/Nav/Comm. During this modification, the Garmin GTX-330 Mode S TIS transponder and newly released GMA-347 (helicopter version) audio panel were also incorporated.

To accommodate for the size of the new Sandel SN340 EHSI, a new panel and console were designed and fabricated for this helicopter.

For more information on this project, please contact Mike Schooley at 321-255-9877 ext. 216 or mschooley@seaerospace.com