



PORTFOLIO

Southeast Aerospace



Eurocopter BO-105 Installation

Southeast Aerospace completed a Garmin retrofit of a BO-105 helicopter. SEA began the installation with several Garmin systems, including GNS-530W NAV/COM/GPS, GDL-69 XM Weather Receiver, and other systems.

The GNS-530W was installed IAW Garmin's new helicopter STC AML. A new instrument panel was fabricated and all overlays were refurbished. In addition to the Garmin installation, all cabin interior parts were refurbished, including: seats, fabric, and carpet. As an added feature, new LED map lights were also installed.



FAA/EASA APPROVED REPAIR STATION # S66R266N
1399 General Aviation Drive | Melbourne Intl. Airport | Melbourne, FL 32935 USA
Tel 321-255-9877 Fax 321-255-9608 | Email sales@seaerospace.com | www.seaerospace.com