

GARMIN® G1000 SPARES



Model:	Part Number:	Exchange Price:	Outright Price:
GDC-74B	011-01110-01	\$1550	\$3950
GDU-1040A	011-00916-10	\$2400	\$6250
GDU-1042	011-01080-00	\$2550	\$5250
GDU-1043	011-01079-00	\$2400	\$6250
GDU-1044B	011-01274-10	\$1950	\$7750
GDU-1050	011-03470-00	\$2950	\$6500
GEA-71	011-00831-00	\$950	\$1995
GTX-33	011-00779-10	N/A	\$1050
GTX-33ES	011-00779-30	\$1350	\$2100
GMA-36	011-01793-00	\$1450	\$5220
GRS-77	011-00868-10	\$1450	\$2750

- ➔ G1000 Component Spares
- ➔ Garmin Certified 8130
- ➔ SV Condition with 6 Month Warranty