

Service Letter: SIL-TS200-2021-001

SERVICE INFORMATION LETTER

FOR

UNDERWATER LOCATING DEVICE (ULD) TEST SET

DUKANE SEACOM, INC. PART NOS.

TS200
and
42A12/1


PREPARED BY:

DUKANE SEACOM, INC

REVISION: A

ENG APPROVED: 

DATE: 2/1/21

QA APPROVED: 

DATE: 2/10/2021

<h1>Service Letter</h1>	Doc No. SIL-TS200-2021-001
	Rev A Date: 1 Feb 2021
SUBJECT: Obsolescence of the TS200 and 42A12/1 ULD Test Sets	

I. PLANNING INFORMATION

A. EFFECTIVITY

This service letter applies to the following Dukane Seacom part numbers:

<u>Part Number:</u>	<u>Nomenclature:</u>	<u>SERIAL NUMBERS:</u>
TS200	Underwater Locating Device (ULD) Test Set	ALL
42A12/1	DK Series Test Set	ALL

B. REASON

Dukane Seacom has recently introduced the TS500 ULD Test Set. This new test set provides expanded test capability for our Recorder Mounted 37.5Khz ULDs (DK120, DK120/90 and DK290) as well as our Airframe Mounted 8.8Khz Low Frequency ULDs (DK180). As a result, Dukane Seacom will be obsoleting the TS200 and 42A12/1 Test Sets.

C. REFERENCES

1. DK120/90 Technical Manual (03-TM-0063)
2. DK100 Series Technical Manual (03-TM-0037)
3. DK290 Technical Manual (03-TM-0090)
4. DK180 Technical Manual (03-TM-0064)

D. DISCUSSION

1. By way of this Service Information Letter, current operators of Dukane Seacom ULDs are notified that the TS200 and 42A12/1 ULD Test Sets will no longer be available for purchase after 1Feb21.
2. Operators may continue to utilize the TS200 and 42A12/1 to test their ULDs
3. Current operators are advised to purchase the TS500 ULD Test Set for future orders.